































190cm

Toute casse des lattes de lit ne peut être prise en charge par la garantie du produit.
All broken slats are not cover by the product warranty.


(1) x1	(2) x2
(3) x2	(4) x1
(5) x24	(6) x24
(7) x12	(8) x2
(9) x22	(10) x24 (M8*40)
(11) x1	(12) x2
(13) x4	




Ax1 	Bx1 
Cx2 	Dx1 
Ex30  (M8*20)	Fx1 
Gx8 	Hx8  (M8*40)
Ix1 	Jx2 
Kx1 	Lx1 
Mx4 	Nx2 
Ox2  85cm	Px4  (M8*50)
Qx6  (M3*20)	Rx2 
Sx6 	Tx1 



11



12



13

